


Danfoss

INSTRUCTIONS AKS Solder Instruction

060R9515




Danfoss
AB603T1.10

2 - 5 sec.



10 - 15 sec.



Danfoss
AB603T1.10

Max.
100°C
(212°F)

Max.
850°C
(1550°F)

3

CuP / AgP

060R9515

Danfoss
AB603T2.11

Max 100°C
(212°F)

